

## Asset Inspection - Separable Part B

**Project:** *Inspection and Defect  
Prioritisation of distribution Lines in North  
Queensland*

**Client:** *Ergon Energy*

**Location:** *Queensland*

**Contract Value:** *AUS <\$8m*

Electrix Pty Ltd was awarded the contract to carry out asset inspections on approximately 80,000 poles per year and Prioritise any defects found .

The works involved:

- Above and below ground inspections;
- Visual inspections of conductors and hardware;
- Replacing Earth guards and stay guards;
- Recording GPS Coordinates;
- Digital photographs of defects;
- Entering data into a central database;

The contract area includes 750kms of coastline from Proserpine, south to the borders of Northern Territory and South Australia some 20hours to the West.

Electrix' contract requires that it manages the inspection process by summarising data gathered during condition assessments of Ergon's assets and enables summary reports to be produced so that appropriate remedial action can be taken .

For further information please contact the Manager Asset Inspection Division on (03) 9399 4688.



Electrix Limited  
208 Hall Street  
Spotswood, Victoria 3015  
Australia  
Phone: +61-3-9399 4688  
Fax: +61-3-9399 4730  
Email: [info@electrix.com.au](mailto:info@electrix.com.au)